# Pitman Arm Puller



#### **Conventional Method**

#### Start: 1:00 p.m

- 1. Put vehicle on hoist. (5 minutes)
- 2. Remove center link assembly from Pitman arm. (5 minutes)
- 3. Remove steering shaft, power steering lines and frame mounting bolts from steering gear . (40 minutes)
- Remove steering gear assembly from vehicle and take to workbench. (40 minutes)
- 5. Attach puller and remove Pitman arm. (10 minutes)
- Install new Pitman arm and torque to specs. (10 minutes)
- 7. Reinstall steering gear in vehicle. (40 minutes)
- Install steering shaft, power steering lines and bolts in steering gear . (40 minutes)
- Install center link assembly to Pitman arm. (5 minutes)
- Refill and bleed air from power steering system. (15 minutes)

#### Finish: 4:30 p.m. Time: 3-1/2 Hours

#### Using OTC 6496 Puller

### Start: 1:00 p.m.

- 1. Put vehicle on hoist. (5 minutes)
- 2. Remove center link assembly from Pitman arm. (5 minutes)
- Loosen or remove steering gear bolt on steering gear (5 minutes)
- 4. Attach puller and remove Pitman arm. (10 minutes)
- Install new Pitman arm and torque to specs. (5 minutes)
- Install or tighten steering gear bolts to frame.
  (5 minutes)
- Install center link assembly to Pitman arm. (5 minutes)

## Finish: 1:40 p.m.

# Time: 40 Minutes

Time Saved: 2 hours 50 minutes!

# Cuts Removal Time from 3-1/2 Hours to 40 Minutes!

- New design saves time, increases productivity.
- Labor intensive removal of steering sector is now unnecessary.
- Compact design of puller allows easy access to the Pitman arm.
- Live center on forcing screw and easy use of a standard wrench results in less effort required.
- Works on most domestic SUVs and pickups.
- Tool is forged steel for durability and long life.
- Pays for itself on its first job.
- Works on the following four-wheel-drive vehicles:

1998 - 2002 Lincoln Navigator

- 1997 2002 Ford F-150 and Expedition
- 1991 2001 Oldsmobile Bravada
- 1991 2001 S10/S15 GM Trucks and Blazers
- 1992 2002 Suburban

SPX

1988 – 2002 GM and Chevy 1/2-, 3/4- and 1-ton pickups

1992 - 2002 Chevy Tahoe and GMC Yukon

No. 6496 - Pitman Arm Puller . Wt., 2 lbs. 8 oz.



Service Solutions, a unit of SPX Corporation

655 Eisenhower Drive, Owatonna, MN 55060-0095 Phone: 507-455-7000, International Sales: 507-455-7223

03-51 Rev.