



655 Eisenhower Drive
 Owatonna, MN 55060 USA
 Phone: (507) 455-7000
 Tech. Serv.: (800) 533-6127
 Fax: (800) 955-8329
 Order Entry: (800) 533-6127
 Fax: (800) 283-8665
 International Sales: (507) 455-7223
 Fax: (507) 455-7063

Form No. 554557

Assembly Instructions

for:

7797

Fuel Injection Diagnostic Kit


No. 7635A

Fuel Injection Pressure Testing Kit

Ensemble de base pour vérifier les pressions de systèmes d'injection

Juego diagnostico para inyección de combustible

- Diagnose fuel pressure problems quickly and accurately.
- Adapter fitting fastens to Schrader valve on fuel rail.
- 0-100 PSI gauge with bleed valve for bleeding air from the system and checking for adequate fuel pump volume.
- Works on GM, Chrysler, Ford and Jeep vehicles with multiport fuel injection.



No. 7665

GM TBI Fuel Pressure Adapter


Adaptateur pour T.B.I. de G.M.

Adaptador para presion de combustible en GM TBI

- Use during fuel pressure checks on most 1983 and newer GM TBI systems.
- Also works with OTC No. 7448 fuel injector cleaning system.
- Allows other brands of adapters and gauges to be easily connected to the 7/16-20 UNF fitting.
- Assembly instructions on back.



WARNING: Wear eye protection that meets ANSI Z87.1 and OSHA standards.




ADVERTENCIA: Use protección en los ojos que cumpla con los requisitos de OSHA y ANSI Z87.1.

ATTENTION: Porter des lunettes de protection qui répondent aux exigences de la norme ANSI Z87.1 et de la OSHA.

ASSEMBLY

1. Disconnect the fuel filter from the fuel line.
2. Thread the ends of the fuel line into the GM TBI Fuel Pressure Adapter (7665). Tighten the fittings using the same specifications outlined in the vehicle service manual for connecting the fuel line to the fuel filter.
3. To adapt a Pressure Gauge Assembly (OTC 7211) or Fuel Injector Cleaner (OTC 7448), first assemble a Quick Disconnect Straight Fitting (OTC 7214A) or Quick Disconnect 90° Elbow Fitting (OTC 7430) to the 7/16-20 UNF x 45° flare fitting. After fittings are assembled, connect the coupler ends to each other.



Sheet No. 1 of 1

Issue Date: Rev. B, August 6, 2014