





655 Eisenhower Drive
 Owatonna, MN 55060 USA
 Phone: (507) 455-7000
 Tech. Serv.: (800) 533-6127
 Fax: (800) 955-8329
 Order Entry: (800) 533-6127
 Fax: (800) 283-8665
 International Sales: (507) 455-7290
 Fax: (507) 455-7063

Form No. 568039


Operating Instructions for: **6290A**

Rev. A March 28, 2013
 © 2013 Service Solutions U.S. LLC

4WD Front Hub Puller



CAUTION: To prevent personal injury, wear eye protection that meets ANSI Z87.1 and OSHA standards.



Location	Make	Year	Model	No. of Bolts	Bolt Circle Diameter	Bolt Size
A	GM	1988 – 2013	1/2-Ton Trucks, Yukon, Tahoe, Suburban	6	139.7 mm (5.50 in.)	14–1.5 mm
B	GM	1988 – 2013	3/4- and 1-Ton Trucks, Suburban	8	165.1 mm (6.50 in.)	14–1.5 mm
D	Ford	1998 – 2013	3/4- and 1-Ton Trucks, Excursion	8	170 mm (6.69 in.)	14–2.0 mm
F	Dodge	1994 – 2013	3/4- and 1-Ton Ram Trucks	8	165.1 mm (6.50 in.)	9/16 in. RH